

CONDITION REPORT

Trico Corporation 1235 Hickory Street Pewaukee, WI 53072 Phone: 800.558.7008 Fax: 262.691.2576

Ticona Polymers Inc

Bishop, TX Boilerhouse-Cogen NORMAL

ECR LCR

NORMAL NORMAL

LOCATION ID: HCCPB-UT-PT-1861 DESCRIPTION: GE Oil Reservoir COMPONENT: Turbine/Dual Axial LUBRICANT: Chevron GST 32 RESERV. CAP: 2000 Gallons

LUBE TIME: Not Provided

TEST SUITE: H002 MACH HRS: Not Provided

SAMPLE DATE: 04/16/2014 REC'D DATE: 04/18/2014 REPORT DATE: 4/23/2014 SPID #: 29660 CNTL #: 5121826 ANALYST: Loede

BATCH #: T140418-012

Analyst Summary:

Routine results were obtained for this sample. The lubricant condition is acceptable.

REPORT RATIN	GS:
--------------	-----

Sample Date	10/08/2013	11/05/2013	12/10/2013	01/09/2014	02/13/2014	03/04/2014	04/16/2014	1	10/14/2013	Lim	nits
Ratings	Normal		Lubricant	Lower Limit	Upper Limit						
PHYSICAL/CHEMICAL PROPERTIES:									Reference	Lower Limit	Opper Limit
Visc 40C, cSt	30.94	30.84	31.14	31.19	31.41	31.41	31.50		30.45	25.60*	41.60*
Visc 100C, cSt									6.62	5.22*	6.96*

									Alert	Alarm
Viscosity Index								183		
Color										
Crackle, Water	N	N	N	N	N	N	N	N		
Crackle, Refridg.	N	N	N	N	N	N	N	N		
Water(KF), ppm				24	28	37	29	37		
Water(%)				0.002	0.003	0.004	0.003	0.004		
Water(FTIR), abs				4.0	5.0	6.0	4.0	4.0		
Oxidation(abs)				4.0	3.0	4.0	4.0	4.0		
Nitration(abs)				2.000	2.000	2.000	2.000	2.000		
TAN(mg KOH)	0.036	0.065	0.029	0.111	0.018	0.049	0.010	0.014		
TBN(mg KOH)										
* RPVOT (Minutes)										
Clear										
Bright										

PARTICULATES	S:								Alert	Alarm
ISO 4406 PC				16/15/13	18/16/13	16/15/11	18/16/13	15/14/12		
DR Trend	4.6	2.4	5.4	9.3	7.2	1.0	4.8			
DL[3.0	1.6	4.2	8.1	6.4	0.8	3.0			
DS	1.6	0.8	1.2	1.2	0.8	0.2	1.8			
Soot				0.0	0.0	0.0	0.0	0.0		

TRΔ	CE ELEME	NTS.								Alert	Alarm
<u></u> ,	Iron	12	0	0	0	0	0	0	0		
	Chromium	2	0	0	0	0	0	0	0		
1_	Aluminum	0	0	0	0	0	1	0	0		
Equipment	Copper	1	1	1	2	2	1	1	0		
ğ	Lead	0	0	0	0	0	0	0	0		
ш	Tin	0	0	0	0	0	0	0	0		
	Silver	0	0	0	0	0	0	0	0		
	Nickel	1	0	0	0	0	0	0	0		
<u>ş</u>	Silicon	1	0	0	0	0	0	0	0		
Contaminants	Sodium	0	0	0	0	0	0	0	0		
tan.	Potassium	1	0	0	3	0	5	2	1		
Š	Boron	0	0	0	0	0	0	0	0		
	Molybdenum	0	0	0	0	0	0	0	0		
	Magnesium	0	0	0	0	0	0	0	0		
ives	Calcium	0	0	0	2	1	1	1	0		
Additives	Barium	0	0	0	0	0	0	0	0		
*	Phosphorus	0	5	5	12	17	11	13	0		
	Zinc	1	2	2	10	8	7	7	2		
_	Cadmium										
Other	Vanadium	0	0	1	0	0	1	0	0		
Ľ	Titanium	0	0	0	0	0	0	0	0		



CONDITION REPORT

Equipment Specific Analysis **Trico Corporation** 1235 Hickory Street Pewaukee, WI 53072 Phone: 800.558.7008

Fax: 262.691.2576

Ticona Polymers Inc

Bishop, TX Boilerhouse-Cogen



LOCATION ID: HCCPB-UT-PT-1861 DESCRIPTION: GE Oil Reservoir COMPONENT: Turbine/Dual Axial LUBRICANT: Chevron GST 32 RESERV. CAP: 2000 Gallons LUBE TIME: Not Provided


TEST SUITE: H002 MACH HRS: Not Provided

SAMPLE DATE: 04/16/2014 REC'D DATE: 04/18/2014 REPORT DATE: 4/23/2014 SPID #: 29660 CNTL #: 5121826


ANALYST: Loede

BATCH #: T140418-012


Rating




Viscosity (Spec. 32.0cSt@40C)




Water KF



Acid No. (mg KOH)




Particle Count (particles/ml)




Particle Count (p/ml)

Date	01/09/14	02/13/14	03/04/14	04/16/14
ISO PC	16/15/13	18/16/13	16/15/11	18/16/13
>4um	552	1676	478	1717
>6um	181	427	174	471
>14um	43	61	19	46
>21um	18	26	3	16
>38um	2	0	0	0
>70um	0	0	0	0


Contaminants in ppm



Wear Metals in ppm



Wear Particle Trend





CONDITION REPORT

Trico Corporation 1235 Hickory Street Pewaukee, WI 53072 Phone: 800.558.7008 Fax: 262.691.2576

Ticona Polymers Inc Bishop, TX

Bishop, TX
Boilerhouse-Cogen



LOCATION ID: HCCPB-UT-PT-1861
DESCRIPTION: GE Oil Reservoir
COMPONENT: Turbine/Dual Axial
LUBRICANT: Chevron GST 32
RESERV. CAP: 2000 Gallons

LUBE TIME: Not Provided
TEST SUITE: H002 MACH HRS: Not Provided

SAMPLE DATE: 04/16/2014 REC'D DATE: 04/18/2014 REPORT DATE: 4/23/2014 SPID #: 29660 CNTL #: 5121826 ANALYST: Loede

BATCH #: T140418-012

WEAR PARTICLE ANALYSIS:

The Wear Particle Concentration increased from 1.0 to 4.8. Analytical results reveal that there are only small quantities of various contaminants and wear debris in this sample. There are no signs of any serious abnormal wearing in this equipment. No maintenance action is required at this time, therefore continue routine operation.

Wear Particle Analysis indicates routine operation.

ANALYTICAL RESULTS:

